

CURRENT VOLTAGE PROBES 2012

GRIDSENSE POWERMONIC KITS AND OPTIONS		PM25	PM35/3G	PM45/3G
PART No.	CURRENT TRANSFORMERS	K1	K1	K1
1ACK1	Converter Current 1A:200mA PM	o	o	
1ACK5	Converter Current 5A:200mA PM	o	o	
1AC10	CT 10A PM45 15mm Iron			o
1ACR100S	CT 100A 15mm Iron (10-120A)	o	o	
1ACR100	CT 100A 52mm Iron (10-120A) Class 0.5 M	o	o	
1AC100S	CT 100A PM45 15mm Iron (10-120A)			o
1ACR500	CT 500A 52mm Iron (50-600A) Class 0.5 M	o	o	
1ASC500	CT 500A PM45 52mm Iron, 50-600A Class 0.5 M, CAT IV 600V			o
1AC500	CT 500A PM45 52mm Iron (50-600A)			o
1ACR1000	CT 1000A Clip-on (100-1200A) Class 0.5M	o	o	
1ACF3000-6	CT 3000A Flexible (100-3600A) - Green	o	o	
1AF3000-6	CT 3000A Flexible 600mm (100-3600A) 600mm length CATIV 600V - Blue			o
1AFF3000-6	CT 3000A Flexible 600mm (100-3600A) - Green	o	o	
1ACF3000-9	CT 3000A Flexible (100-3600A) - Blue	o	o	
1AF3000-9	CT 3000A PM45 900mm Flexible (100-3600A) 900mm length CATIV 600V - Blue			o
PART No.	VOLTAGE CABLES	K1	K1	K1
1AVL3	3 Wire (Delta) voltage cable assy to fused end	o	o	
1AVL4	4 Wire (3P+N) cable assy to fused end	o	o	
1AVL4C2	4-Wire (3P+N) cable harness fused with clamps	1	1	
1AVL6C2	6 Wire (3P+3N) cable assy to fused end	o	o	
1AAC4TE	Tinned End fused attachment for 4-Wire voltage cable	1	1	
10169	2A HRC Fuse for voltage cable	4	4	
1AAC4BC	Banana Plug fused attachment (3P+N) with small clamps for 1AVL4	o	o	
1AAC4TE	Tinned End fused attachment (3P+N) for 1AVL4	o	o	
1AAC6BC-1	Banana Plug fused attachment (3P+N) with small clamps for 1AVL6C2	o	o	
1AAC6TE	Tinned End fused attachment (3P+3N) for 1AVL6C2	o	o	
1AVL5-C	5-Wire (3P+N+G) cable harness fused with large clamps, CAT IV 600V			o
1AVL5-B	5-Wire (3P+N+G) cable harness fused with banana plugs & croc clamps, CAT IV 600V			1
1AVL8-B	8-Wire (3P+3N+2G) cable harness fused with banana plugs & croc clamps, CAT IV 600V			o
1AVL8-C	8-Wire (3P+3N+2G) cable harness fused with clamps, CAT IV 600V			o

o	Optional Accessory
n	Number of accessory items included in Kit